

10/26 Started beamlines

Visit 10 AM Monday

drop 2x2 mm }
1.5 mm depth of view } then zoom way in to see 1 micron
size shapes

see things that are 1 micron in size

3000 inspections/week

inspect 6 times week

1st pass

clear / not clear

1/week for 12 weeks

2nd pass

want turn it 3 knuckles

not clear

4 ~~0~~ °C

39.2°F

12 ~~0~~ °C

53.6°F

26 ~~0~~ °C

68.0°F

Step 1 indexer that shows ~~sizes~~ pictures

Step 2 sort clear images from not clear

Step 3 sort not clear images

Ident crystal 100x100x100 microns

Variable ~~zoom~~

need database to query picture files by • date
• temp
• shape

Enclosure 2